


Atmosphere Cantilever Workstation/Wave




Assembly steps

1. Place the top upside down. Screw three Part A into the top (for modesty panel attachment).
2. Lift and locate the modesty panel onto the three Part A in the top. Do not tighten the three minifix cams.
3. Screw six Part A into the uprights on the two leg frames.
4. Fix the leg frames onto the desk top, locating the three Part A on each leg frame with the three minifix cam holes on the modesty panel. Tighten minifix cams to secure the leg frames to the modesty panel.
5. Screw six Part B through the leg frames into the top.
6. Tighten the three minifix cams in the modesty panel.
7. Push Parts C into the appropriate places to finish the desk.

Fittings supplied




Part A
Minifix bolts M6
Quantity=9



Part B
M6 Flat head bolt
Quantity = 6



Part C
Minifix cover
Quantity=9



Tools required


Pozi head screw driver



Allen key (4mm)

Wave desk shown

Atmosphere Slab Workstation/Wave



Assembly steps

1. Place the top upside down. Screw three Part A into the top for (modesty panel attachment).
2. Lift and locate the modesty panel onto the three Part A in the top. Do not tighten the three minifix cams.
3. Screw six Part A and push four Part B into the top for slab panel attachment. Knock two Part D into rail ends.
4. Screw six Part A into the appropriate holes on the slab panel to locate with modesty panel
5. To add the Slab panel, lift the modesty slightly and locate three Part A on one slab leg with the three minifix cam holes on one end of the modesty panel. Then lower the both the slab and modesty panel onto the two Part A/two Part B in the top. Repeat this process for the other slab panel.
6. Tighten the nine minifix cams in the modesty panels and the two in each slab panels.
7. Push Parts C into the appropriate places to finish the desk.

Fittings supplied




Part A
Minifix bolts M6
Quantity=15



Part B
Wood dowels
Quantity = 8



Part C
Minifix cover
Quantity=13




Part D
Plain silver bung
Quantity=2

Tools required



Pozi head screw driver



Nylon hammer

Wave desk shown