SPECIAL NOTICE

DO NOT TIGHTEN CAMS ON TOP PANEL UNTIL

DOORS ARE INSERTED INTO TOP/BTM TRACKING

AND ARE RUNNING FREELY