Conference Table Assembly Sheet

LIST OF COMPONENTS: -

- 1 TOP
- 4 TABLE PLATES
- 4 TABLE LEGS
- 20 10 x 3/4 PAN POZI
- 4 10mm BOLT
- 1. Remove the two 8 X 1½ csk screws from each packing piece (dispose of screws and packing pieces.)
- 2. Screw table plates onto underside of top using 10 X ¾ pan pozi screws into 3mm holes provided, ensuring you first position 10mm bolt through underside of table Plate.
- 3. Screw table legs onto 10mm bolt now located in table plate

Instruction Leaflet No 001