

Overhang Top with Table Legs Assembly Sheet

LIST OF COMPONENTS: -

1	TOP
2	TABLE PLATES
2	TABLE LEGS
10	10 X $\frac{3}{4}$ PAN POZI
1	10mm BOLT

- 1.Remove the one 8 x 1 $\frac{1}{2}$ csk screws from each packing piece (dispose of screws, packing pieces and packaging materials only after product has been assembled and inspected.)
- 2.Screw table plates onto underside of top using 10 x $\frac{3}{4}$ pan pozi screws into 3mm holes provided, ensuring you first position 10mm bolt through underside of table plate.
- 3.Screw table legs onto 10mm bolt now located in table plates.
- 4.Attach top to linking brackets located on the end of cant/slab ends on desk.